



An Affiliate of
**Underwriters
Laboratories Inc.**

UL Korea Ltd.
33rd Floor Star Tower
737 Yeoksam-dong Kangnam-gu
Seoul, 135-984
Korea
www.ulc.co.kr
tel: 822 2009 9000
fax: 822 2009 9400

R21544, 03CA30277

October 14, 2003

SAM HOON MACHINERY COMPANY
KYONGGI-DO, KOREA



Attention: Mr. Jong-Sam Moo

Fax: 82-32-661-3505

Reference: Fire Test at KICT Dated May 29, 2003 and UL 10B
Project No. 03CA30277

Subject: Application of Fire Door Frames

**NOTICE OF COMPLETION OF ENGINEERING INVESTIGATION
AND THE INITIAL PRODUCTION INSPECTION (IPI) ARRANGEMENT**

Dear Mr. Jong-Sam Moo:

This letter is sent on behalf of Underwriters Laboratories Inc. pursuant to the Corporate Services Agreement between UL Korea, Ltd. and UL.

We have completed our engineering investigation under the above project number 02CA30277 and find the product complies with the applicable requirements.

NO subject products bearing UL Marks / references are allowed to be shipped out from the manufacturing location of

**Manufacturers: SAM HOON MACHINERY CO
168-15 YONGTAN-DONG
CHUNGJU-SHI
CHUNGCHONGBUK-DO KOREA**

until the Initial Production Inspection (IPI) is successfully performed by a UL representative at the aforementioned manufacturing location.

It is the responsibility of you, the Applicant, to clearly convey the need to successfully complete IPI before shipment to your manufacturer. The IPI package is being prepared and will be sent to our inspection center nearest to your factory. The contact information of the inspection center is provided at the end of this letter so that they can be contacted to schedule for the IPI and to answer any questions that you may have regarding IPI.

Upon completion of the IPI, SAM HOON MACHINERY CO will receive UL Listing for Fire Door Frames in accordance with UL 63 with the following parameters:

An independent organization working for a safer world with integrity, precision and knowledge.



R21544, 03CA30277

October 14, 2003

Page 2

Door Frames for use as a component in fire door assemblies that meet the requirements of UL10B (neutral pressure):


Three sided frames without transom bars (single swing and pairs) (welded, knockdown)

Records covering the products are now being prepared and will be sent to you in the near future. Underwriters Laboratories Inc. has been instructed to send an invoice to you for the charges accrued.

Productswwhich bear the UL Mark shall be identical to those which were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, authorization to use the UL Mark may be withdrawn and products that bear the UL Mark may have to be revised (in the field or at the manufacturer's facility) to bring them into compliance with UL's requirements.


In any correspondence concerning this investigation, please refer to the above file and project number.

Very truly yours,



JaeHan Bae
Associate Project Engineer
Conformity Assessment Services
UL Korea, Ltd.
Phone: 82-2-2009-9341
Fax: 82-2-2009-9483
E-mail: JaeHan.Bae@kr.ul.com

Reviewed by:



Howard J. Gruszynski
Staff Engineer
Conformity Assessment Services
Fire Protection Division
E-mail: Howard.J.Gruszynski@us.ul.com

c: Seoul Inspection Center
Attn: Ms. Hye-In Kim
Tel: 82-2-767-0508